

Message

From: Spurlin, Steve [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=7AE2616803EE42B9B9F19A2B12FCE89F-SPURLIN, STEVE]
Sent: 4/19/2019 7:19:52 PM
To: Wyatt, John M. [JMWyatt@colpipe.com]
CC: todd.taylor@tetrattech.com; Glaze, Gregory [GGlaze@colpipe.com]; Cazares, Juan [JCazares@colpipe.com]
Subject: Re: Colonial Nashville Airport Update 4/19

Thanks for update.

Sent from my iPhone

On Apr 19, 2019, at 2:10 PM, Wyatt, John M. <JMWyatt@colpipe.com> wrote:

Steve,

We continue to recover out of both trenches above the creek. 3 dams have been installed at the seep area to prevent a majority of the product from reaching the creek. However, there are still occasional drops of sheen observed in the creek at the southernmost end of the seep.

Attached is the map updated interceptor trench 5. If you have any questions, let me know.

Thanks,

John M. Wyatt

Environmental Program Manager
Southeast District

Colonial Pipeline Company
4295 Cromwell Rd. #311
Chattanooga, TN 37421
Ph: 423-713-7568
Fax: 770-754-8119

Colonial Pipeline Notice - This e-mail message (including any attachment) contains information that may be confidential, be protected by attorney-client or other privilege, or constitute non-public information. If you are not the intended recipient, please notify the sender by electronic mail or telephone and delete the original message without making any copies. Use, dissemination, distribution, or reproduction of this message by unintended recipients is not authorized and may be unlawful.

<Colonial Nashville Airport 041919.pdf>